

# QUICKSTART GUIDE

FINGER  
CRAMP

## ULTIMATE Loopy Edition 3DS CAPTURE BUNDLE



SINGLE USB-C  
CAPTURE  
AND CHARGE




LOOPY CONTROLLER KIT AND PI HDMI TV KIT  
AVAILABLE AS OPTIONAL UPGRADES

# QUICK-START V2 (Loopy)

## PC


1. Plug in the USB drive. Drag software capture folder to your PC.
2. Install the Driver in the 3dscapture\*\*\driver folder
3. Plug the USB-C Cable from your PC into your 3DS USB-C (Middle Port)
4. Launch 3ds\_capture.exe

Main Capture and Charge USB-C Port.



### FC Controller Port

(Next to R Button - USE only FC Dongles! Logo Side Face up.)



“DO NOT PLUG IN A REGULAR USB-C CABLE INTO THE CONTROLLER EXTENSION PORT, YOU RISK LONG TERM DAMAGE.

Use a keyboard with th raspberry PI to change settings.

## PI / HDMI TV

The PI4 is an add-on for the Capture setup. It uses the USB out from the 3DS and display the signal. It helps make it possible to display the New 3DS to your TV through HDMI. The PI can output both screens at 60 fps, it can be changed in the settings. [CC3DSFS By Lorenzone is available here.](#)

### Instructions

1. Connect the HDMI, Keyboard and power adapter to your PI4.
2. Plug the USB-C from your New 3DS into your PI.
3. Turn on the PI and it will autoboot into the Software.

Note: The New 3DS can be connected after PI is turn on. Please click connect button



**THANK YOU FOR  
SHOPPING WITH US.  
ENJOY YOUR 3DS!**