

FINGERCAMP EXCLUSIVE

QUICKSTART GUIDE

ULTIMATE 3DS CAPTURE BUNDLE



**SINGLE USB-C
CAPTURE
AND CHARGE**

KATSUKITY CAPTURE KIT INSTALLED
OPTIONAL LOOPY KIT UPGRADE AVAILABLE

QUICK-START

PC

1. Drag software capture folder to your PC.
2. Install the Driver in the new3DSview_ver113\driver folder
3. Plug the USB-C Cable from your PC into your 3DS USB-C (Middle Port)
4. Launch new3DS_view.exe



Main Capture and Charge USB-C Port.



FC Controller Port

(Next to R Button - USE only FC Dongles! Logo Side Face up.)



“DO NOT PLUG IN A REGULAR USB-C CABLE INTO THE CONTROLLER EXTENSION PORT, YOU RISK LONG TERM DAMAGE.



Use a keyboard with th raspberry PI to change settings.

PI 4 / HDMI TV

The PI4 is an add-on for the Capture setup. It uses the USB out from the 3DS and display the signal. It helps make it possible to display the New 3DS to your TV through HDMI. The PI can output both screens at 60 fps, it can be changed in the settings.


Instructions

1. Connect the HDMI, Keyboard and power adapter to your PI4.
 2. Plug the USB-C from your New 3DS into your PI4.
 3. Turn on the PI 4 and it will autoboot into the Software.
- Note: The New 3DS must be plugged in before you turn on the PI

Important!

There is audio lag if you use usb audio. I highly recommend getting an “HDMI Embedder” and take the audio from the NEW 3DS XL headphone jack.

OPTIMAL HARDWARE FLOW CHART



**THANK YOU FOR
SHOPPING WITH US.
ENJOY YOUR 3DS!**